DRAWING NUMBER

SIZE

SCALE:

DATE:

APPROVED BY:

CHECKED BY: ద

DRAWN BY:

FIGURE NUMBER

TOLERANCE AND CHANGE WITHOUT NOTICE

NONE


WE CAN ASSUME NO RESPONSIBILITY FOR USE OF SUPERSEDED OR VOID DATA

MEMBER OF MORRIS GROUP IN FERNATIONAL POST OFFICE BOX 3237 MONTGOMERY, ALABAMA 36109-0237 (USA) TEL: 334-277-8520 FAX: 888-377-7818 www.jrsmith.com


LOCATION

DISTRIBUTION UNIT


FUNCTION: Used to divide the output of a trap primer where 2 to 4 trapped drains are installed.




2683-1 (4) 1/4" Male Sweat End **Outlets**




(2) Closed **Ends**



2683-4 (3) 1/4" Male Sweat End **Outlets**



Outlets



REGULARLY FURNISHED:

Lead Free Brass with 1/2" NPT Swivel Inlet Connections as illustrated. Outlet Connections as per Figure Number.



(2) Closed Ends

B A	12-2-19 5-30-19	Revised Drawing, Added UPC Revised Outlet Descriptions	MW TBW	CL DP	_	VOLUME CUBIC FEET	FIGURE NUMBER 2683
REV.	DATE	DESCRIPTION	BY	CKD. BY			2000

S2683BS

DRAWING NUMBER

JAY R. SMITH MFG. CO. ® MEMBER OF MORRIS GROUP INTERNATIONAL MEMBER OF MORRIS GROUP INTERNATIONAL POST OFFICE BOX 3237 MONTGOMERY, ALABAMA 36109-0237 (USA) TEL: 334-277-8520 FAX: 888-377-7818 www.jrsmith.com LOCATION

DISTRIBUTION UNIT

WE CAN ASSUME NO RESPONSIBILITY FOR USE OF SUPERSEDED OR VOID DATA

DATE:

NONE

SCALE

APPROVED BY

CHECKED BY

DRAWN BY:

DIMENSIONS ARE SUBJECT TO MANUFACTURERS TOLERANCE AND CHANGE WITHOUT NOTICE

FIGURE NUMBER

В

Α

